



IN

INDIA

Diagram / Parts List

GD002G

CORDLESS DIE GRINDER



This exploded view diagram illustrates the assembly of a Makita power tool. The components are numbered as follows:

- 1, 2:** Small fasteners or pins.
- 3:** A long screw.
- 4:** A large cylindrical component, likely the motor housing.
- 5:** A small screw.
- 6:** A long, thin component, possibly a blade or guard.
- 7:** A small circular component.
- 8:** A small rectangular component.
- 9:** A small spring.
- 10:** A small rectangular component.
- 11:** A small circular component.
- 12:** A small rectangular component.
- 13, 14, 15, 16:** A series of small circular components, likely washers or spacers.
- 17:** A long shaft or pin.
- 18, 19:** Small circular components.
- 20, 21, 22:** Small fasteners or pins.
- 23:** A small rectangular component.
- 24, 25:** Small circular components.
- 26, 27:** Small fasteners or pins.
- 28:** A small circular component.
- 29, 30:** Small fasteners or pins.
- 31:** A small circular component.
- 32:** A large circular component, likely a gear or pulley.
- 33:** A large gear or pulley.
- 34:** A small circular component.
- 35:** A large circular component, likely a gear or pulley.
- 36:** A small rectangular component.
- 37:** A large rectangular component, likely a base plate or housing.
- 38:** A small rectangular component.
- 39:** A small rectangular component.
- 40:** A large rectangular component, likely a base plate or housing.
- 41:** A small rectangular component.
- 42:** A small rectangular component.

GD002G / CORDLESS DIE GRINDER

[illegible]

A:GD002GZ(N)
B:GD002GM201(H)

Interchange
O : Yes
X : No
< : the new part can be substituted for the current.
> : the current part can be substituted for the new.
S : Interchangeable as a set.